




Bank Erosion Monitoring



Products	A database showing the response of the banks to fluvial processes considering overbanking, tree removal, and bank modification will be developed in the first year. An empirical model of the expected bank erosion along the Middle Rio Grande will be developed from the data collected in future years.
Benefits	Restoration decision-makers can use the database and/or the empirical model to predict the expected bank response due to overbanking, tree removal, and/or bank modification. In addition, the data collected will be useful for the evaluation and calibration of sediment transport models.
Issue	Restoration along the Rio Grande consists of a number of different projects from removal of non-native species to removal of jetty-jacks to reworking of channel banks and promoting overbank flooding. To reestablish ecological health of the bosque, it is desired to have the floodplain reconnected with the river channel. At the same time, the Rio Grande flows through a major metropolitan area where flood control is necessary. It is necessary to understand the variables affecting bank erosion to be able to make appropriate decisions for restoration activities whether they include removing Russian olives along the bank or mechanically altering the bank to promote overbank flooding. Predicting bank erosion is also useful for managing loss of habitat and cultural artifacts.
Description	<p>Bank erosion is being monitored by two methods: erosion pins and LiDAR scanning. Erosion pin sites established before June 2006 are being monitored as part of this project. In addition, experiments located downstream of the Calabacillas Arroyo have been established. LiDAR scanning provides a means to remotely collect continuous data on bank geometry. LiDAR scans are being conducted at the erosion pin sites as well as other locations of interest, such as the diversion dam site. Repeat measurements allow for the derivation of volumetric estimates of channel bank modification.</p> <p>The bank erosion data will be evaluated to determine the impact of river flows and levels, bank vegetation, bank geometry and soil type on the resulting bank stability. We seek to</p>

identify key factors and consider possible predictive approaches addressing bank modification.

Sponsor Southwest Urban Flood Damage Program (SWDP). One of the experimental sites was originally funded through a National Science Foundation – Research Experiences for Undergraduates program.

Points of Contact John Stormont, University of New Mexico
Email: jcstorm@unm.edu
Phone: 505-277-6063

Julie Coonrod, University of New Mexico
Email: jcoonrod@unm.edu,
Phone: 505-277-3233

Tim Wawrzyniec, University of New Mexico
Email: tfw@unm.edu
Phone: 505-277-2740

Lisa Hubbard, Program Manager, ERDC, Coastal and Hydraulics Laboratory
Email: Lisa.C.Hubbard@usace.army.mil
Phone: 601-634-4150

Partners USACE – Albuquerque District.